

Oil Field Environmental Incident Summary

Incident: 20150605162928 **Date/Time of Notice:** 06/05/2015 16:29
Responsible Party: HESS TIOGA GAS PLANT LLC
Well Operator: HESS TIOGA GAS PLANT LLC
Well Name: Pipeline
Field Name: PLEASANT VALLEY **Well File #:**
Date Incident: 6/4/2015 **Time Incident:** 17:00 **Facility ID Number:**
County: WILLIAMS **Twp:** 156 **Rng:** 95 **Sec:** 2 **Qtr:** NE
Location Description: Gas Gathering Pipeline ROW

Submitted By: Jason Henry **Received By:**
Contact Person: Jason Henry
3015 16th Street SW, Suite 20
Minot, ND 58701

General Land Use: Cultivated **Affected Medium:** Topsoil

Distance Nearest Occupied Building: 0.5 Mile
Distance Nearest Water Well: 0.5 Mile

Type of Incident: Pipeline Leak

Release Contained in Dike: Yes - On Pipeline ROW

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil					1	barrels
Brine						
Other	0.5	Barrels				

Description of Other Released Contaminant:

Condensate and natural gas from a 6-inch gas gathering pipeline.

Inspected: **Written Report Received:** 5/2/2016 **Clean Up Concluded:** 6/15/2015

Risk Evaluation:

The release has been secured, and the pipeline was isolated until repairs can be made. GPS coordinates for the release N 48.370295, W 102.860814

Areal Extent:

Approximately 300 square feet along the pipeline ROW.

Potential Environmental Impacts:

There was no surface water observed in the immediate vicinity of the release location. The pipeline will be repaired, and any impacted soil that is encountered during the excavation work will be transported off-site for proper disposal.

Action Taken or Planned:

The pipeline will be repaired, and any impacted soil that is encountered during the excavation work will be transported off-site for proper disposal.

Wastes Disposal Location: At a properly permitted disposal facility.

Agencies Involved:**Updates**

Date: 6/5/2015 **Status:** Reviewed - Follow-up Required

Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to report, release impacted areas off location. Followup is required.

Date: 6/19/2015 **Status:** Inspection

Author: Kangas, Kathleen

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Repair is complete. Crew on site placing clean soil. Contaminated soil has been removed.